




T1-2 & T1-4 Tapping Machine

Description

Item

- | | |
|--------------------------------------|-------------------|
| 1. Feed Screw Assembly | T1-FSA |
| 2. Power Bracket Set Screws | T1-PBSS |
| 3. Power Bracket Spacers | T1-PBS |
| 4. Power Bracket Frame | T1-PB |
| 5. Milwaukee # 1675-6 | T1-HOG-1675-6 |
| 6. Chuck Key | T1-CK |
| 7. Brass Packing Assembly | T1-Brass Packing |
| 8. Boring Bar Packing | T1-ORNG-P |
| 9. Packing External O-Rings | T1-ORNG-P |
| 10. T1-M Adaptor Housing | T1M-IP-000 (Call) |
| 11. T1-M Adaptor O-Ring Replacement | T1-ORNG-MIP |
| 12. Adaptor Housing w/ Packing | T1-Packing |
| 13. Adaptor O-Ring Replacement | T1-ORNG-P |
| 14. High Temp Packing | T1S-STM-450 |
| 15. High Temp Gasket Replacement | 3125SS |
| 16. High Temp Gasket | 3125SS |
| 17. Rail Flange Assembly | T1-RFA |
| 18. Adaptor Housing Retaining Screws | T1-AHRS |
| 19. 1/4" Ball Valve | T1-BV-125 |
| 20. 1/4" Nipple | T1-BVN-125 |

Description

Item

- | | |
|--|----------------|
| 21. 1" Threaded Adaptor | T1A-IP-100 |
| 22. 1 1/2" Threaded Adaptor | T1A-IP-150 |
| 23. 2" Threaded Adaptor | T1A-IP-200 |
| 24. 2 1/2" Threaded Adaptor | T1A-IP-250 |
| 25. 3" Threaded Adaptor | T1A-IP-300 |
| 26. 4" Flanged Adaptor 150lb. | T1A-TFL-150 |
| 27. 4" Flanged Adaptor 300lb. | T1A-TFL-300 |
| 28. 1/8" x 18 solid drill | T1-BBT-1800SC |
| 29. 7/8" x 18 solid drill | T1-BBT-1801SC |
| 30. 18"D-Boring bar for 3/4"-1 1/4" taps | T1-BBD-1800 |
| 31. Boring Bar set screw for pilot drill | T1-BBD-1800-SS |
| 32. 1/4" x 4" Pilot Drill | T1P-1402-RRW |
| 33. 1/4" Drill Retainer wire | 9666-K29 |
| 34. 18"P-Boring bar for 1 1/2"-2" taps | T1-BBP-1800 |

Description

Item

- | | |
|--|---------------------|
| 35. Mandrel w/set pins | T1-BBM-3000-MN |
| 36. 3/8" x 4" Pilot Drill | T1P-3840-RRW |
| 37. 24" P-Boring bar for 1 1/2"-3" taps | T1-BBP-2400 |
| 38. Holesaw cutter in various sizes | (see www.2lbin.com) |
| 39. 3/8" x 4" Pilot Drill (5" available) | T1P-3850-RRW |
| 40. 3/8" Drill Retainer wire | 9666-K36 |
| 41. 30" P-Boring bar for 1 1/2"-4" taps | T1-BBP-3000 |
| 42. Mandrell Feed Nut | T1-BBM-3000-NUT |
| 43. Mandrell w/set pins | T1-BBM-3000-PIN |