

T1-Air Drive Hot Tapping Machine

Description

Description	Item #
1. Feed Screw Assembly	T1-FSA
2. Power Bracket Set Screws	T1-PBS
3. T1 Air Drive	T1-AD
4. Elbow	T1-ADFE
5. Air Drive Filter	12-ADF
7. Brass Packing Assembly	T1-Brass Packing
8. Boring Bar Packing	T1-ORNG-P
9. Packing External O-Rings	T1-ORNG-P
10. T1-M Adaptor Housing	T1M-IP-000 (Call)
11. T1-M Adaptor O-Ring Replacement	T1-ORNG-MP
12. Adaptor Housing w/ Packing	T1-packing
13. Adaptor O-Ring Replacement	T1-ORNG-P
14. High Temp Packing	T1S-STM-450
15. High Temp Gasket Replacement	3125 SS
16. High Temp Gasket	3125SS
17. Rail Flange Assembly	T1-RFA
18. Adaptor Housing Retaining Screws	T1-AHRS
19. 1/4" Ball Valve	T1-BV-125
20. 1/4" Nipple	T1-BVN-125

Description

Description	Item #
21. 1" Threaded Adaptor	T1A-IP-100
22. 1 1/2" Threaded Adaptor	T1A-IP-150
23. 2" Threaded Adaptor	T1A-IP-200
24. 2 1/2" Threaded Adaptor	T1A-IP-250
25. 3" Threaded Adaptor	T1A-IP-300
26. 4" Flanged Adaptor 150lb.	T1A-TFL-150
27. 4" Flanged Adaptor 300lb.	T1A-TFL-300
28. 1/8" x 18 solid drill	T1-BBT-1800SC
29. 7/8" x 18 solid drill	T1-BBT-1801SC
30. 18" D-Boring bar for 3/4"-1 1/4" taps	T1-BBD-1800
31. Boring Bar set screw for pilot drill	T1-BBD-1800-SS
32. 1/4" x 4" Pilot Drill	T1P-1402-RRW
33. 1/4" Drill Retainer wire	9666-K29
34. 18" P-Boring bar for 1 1/2"-2" taps	T1-BBP-1800

Description

Description	Item #
35. Mandrel w/set pins	T1-BBM-3000-MN
36. 3/8" x 4" Pilot Drill	T1P-3840-RRW
37. 24" P-Boring bar for 1 1/2"-3 taps	T1-BBP-2400
38. Holesaw cutter in various sizes	(see www.2lbin.com)
39. 3/8" x 4" Pilot Drill (5" available)	T1P-3850-RRW
40. 3/8" Drill Retainer wire	9666-K36
41. 30" P-Boring bar for 1 1/2"-4" taps	T1-BBP-3000
42. Mandrell Feed Nut	T1-BBM-3000-NUT
43. Mandrell w/set pins	T1-BBM-3000-PIN

